

**From:** [Sales, James](#)  
**To:** [Moore, Gary](#)  
**Cc:** [Mayer, Richard](#); [Roberts, Lou](#); [Delgado, Paige](#)  
**Subject:** RE: Frank J. Doyle Transformer Salvage Site, Leonard, TX  
**Date:** Wednesday, June 20, 2018 7:37:15 AM

---

Lou and I have worked on this—It was not put on the NPL, and since the Doyle's have no money to clean it up, EPA has not pursued enforcement action. The TCEQ is involved with the site, and they have been trying to get some action on it through their enforcement program—to no avail I believe so far.

---

**From:** Moore, Gary  
**Sent:** Wednesday, June 20, 2018 6:49 AM  
**To:** Sales, James <sales.james@epa.gov>  
**Cc:** Mayer, Richard <mayer.richard@epa.gov>; Roberts, Lou <Roberts.Lou@epa.gov>; Delgado, Paige <Delgado.Paige@epa.gov>  
**Subject:** Frank J. Doyle Transformer Salvage Site, Leonard, TX

Jim:

Can you look at the records for this site and let me know what actions were taken by the TSCA Enforcement Group over the years to have this company address the PCB spills?

Lou, I have added you since you may have some history.

Thanks

**Gary W. Moore (6SF-ER)**  
**Federal On-Scene Coordinator**  
**U.S EPA Region 6**  
**1445 Ross Ave, Suite 1200**  
**Dallas, TX 75202-2733**  
**Cell: 214.789.1627**  
[moore.gary@epa.gov](mailto:moore.gary@epa.gov)